
Inventors: Ernest S. Cohen Attorney: Peter M. Ullman Sheet 1 of 6


Phone: (215) 568-3100

1/6



Docket No.: MSFT-2820/306478.1

App No.: Not Yet Assigned Filed: Herewith
Title: LAZY FLUSHING OF TRANSLATION LOOKASIDE BUFFERS
Inventors: Ernest S. Cohen
Attorney: Peter M. Ullman Phone: (215) 568-3100
Sheet 1 of 6



Docket No.: MSFT-2820/306478.1

App No.: Not Yet Assigned Filed: Herewith

Title: LAZY FLUSHING OF TRANSLATION LOOKASIDE BUFFERS
Inventors: Ernest S. Cohen

Attorney: Peter M. Ullman Phone: (215) 568-3100

Sheet 1 of 6 3/6 RHS (<u>360</u>) LHS (350) 304 302 306(1) 308(1) 306(2) 308(2) 306(n) 308(n) \_\_ 310 Curtained memory 312

FIG. 3

Docket No.: MSFT-2820/306478.1

App No.: Not Yet Assigned Filed: Herewith

Title: LAZY FLUSHING OF TRANSLATION LOOKASIDE BUFFERS

Inventors: Ernest S. Cohen

Attorney: Peter M. Ullman Phone: (215) 568-3100

Sheet 1 of 6

4/6




FIG. 4

Docket No.: MSFT-2820/306478.1

App No.: Not Yet Assigned Filed: Herewith
Title: LAZY FLUSHING OF TRANSLATION LOOKASIDE BUFFERS

Inventors: Ernest S. Cohen Attorney: Peter M. Ullman Sheet 1 of 6

Phone: (215) 568-3100

5/6




FIG. 5

Docket No.: MSFT-2820/306478.1


App No.: Not Yet Assigned Filed: Herewith Title: LAZY FLUSHING OF TRANSLATION LOOKASIDE BUFFERS

Inventors: Ernest S. Cohen Attorney: Peter M. Ullman Sheet 1 of 6

614

Phone: (215) 568-3100





<u>FIG. 6</u>